




















A X5	B X2	C X1	D X1
			
E X1	F X2	G X4	H X4
		 1/4"X15MM	 1/4"X20MM
I X10	J X5	K X10	L X14
 1/4"X57MM	 1/4"X51MM	 Ø16X16MM PC WASHER	 Ø14MM
M X10	N X1	O X6	P X24
 Ø16MM		 1/4"X35MM	
Q X5			
 CUSHION			


1-1



1-2




1-3




2-1


Step 2




2-2




2-3




3-1



3-2



3-3



3-4

